



Document Description: TSB-CP150 V1.00.04 SOFTWARE RELEASE	Document Number: 20013987 Version: A
	Page 1 of 2
Printed or electronic versions of this document not accessed directly from the designated Welch Allyn Controlled Quality Information System are For Reference Only.	

<h2 style="margin: 0;"><i>Technical Service Bulletin</i></h2>			
Product:	CP150 Electrocardiogram	Date:	2015-04-09
Subject:	CP150 V1.00.04 SOFTWARE RELEASE		
HW Version(s) Affected:	CP150-3ZHC-CN and CP150-4ZHC-CN	SW Version(s) Affected:	V1.00.03 and below
Serial Numbers Affected:	N/A	Lot or Date Code Affected:	N/A
Classification: As Needed			
Distribution: <input checked="" type="checkbox"/> Customer Care <input checked="" type="checkbox"/> Product Service <input checked="" type="checkbox"/> Field Service <input checked="" type="checkbox"/> ASPs <input type="checkbox"/> Distributors <input type="checkbox"/> Customers <input checked="" type="checkbox"/> Company Confidential			
<u>THIS DOCUMENT CONTAINS CONFIDENTIAL INFORMATION</u> It can be distributed or made available to only those individuals, companies, and organizations which have current Welch Allyn Confidentiality Agreements, and have a need to know.			
Training Required:		Yes	
Summary:	The Welch Allyn Diagnostic Cardiology Team is releasing a new version of software for CP150 electrocardiographs in the China market only. This version will improve the functionality outlined below. This update incorporates every benefit provided by all prior software updates before v1.00.03.		

Issue:	The new software includes: <ul style="list-style-type: none"> Correction of the Chinese age unit of measure Physician and comments entry support Additional global measurements
Reference to Standards:	<ul style="list-style-type: none"> 21 CFR Part 820, ISO 13485, MPD SOP-0002

Document Description: TSB-CP150 V1.00.04 SOFTWARE RELEASE	Document Number: 20013987 Version: A
	Page 2 of 2
Printed or electronic versions of this document not accessed directly from the designated Welch Allyn Controlled Quality Information System are For Reference Only.	

Service Strategy:	<p>The V1.00.04 software update is for China market only.</p> <p>China customers can update their CP150s to software V1.00.04 to add the above mentioned software features.</p> <p>Take note that this software version does not support Spirometry functions or any other additional functions exclusively made available in the use of software version V2.xx.xx.</p> <p>With this release, 20013803 TSB-CP150 V1.00.03 SOFTWARE RELEASE and CP150-0028 Software Update Kit (V1.00.03) will be made obsolete.</p>
Required Materials:	<p>CP150-0032 / SERV KIT, SOFTWARE UPDATE V1.00.04</p> <p>Customer Letter 723447</p>
Update Procedure:	<p>The software update can be delivered via the Software Update only.</p> <p>Software Update Kit: Refer to Customer letter 723447 (Shipped with Software Update kit, P/N CP150-0032) for detailed software update instructions.</p>
Quality Documents:	<p>All service centers using SAP to record service transactions: For each product serviced, record the service activity in SAP.</p> <p>All other service centers and Field Service: For each product serviced, complete and file a service report and attach to the service DHR.</p>

Notes:

1. Contact the Welch Allyn Complaints Department to initiate or process a medical device complaint resulting from this or other issues.
2. Drawings, illustrations, and part numbers in this document are for reference purposes only and subject to change.

End of Bulletin

Revision History

Version	Sec, Pg, Para Changed	Change Made	Date Version Created	Version Created By (initials)
A	N/A	Initial Release	2015-04-09	AO

THIS INFORMATION IS THE PROPERTY OF WELCH ALLYN, INC. AND AS SUCH SHALL NOT BE REPRODUCED, COPIED, OR USED AS A BASIS FOR THE MANUFACTURE OR SALE OF EQUIPMENT OR DEVICES WITHOUT THE EXPRESS WRITTEN PERMISSION OF WELCH ALLYN, INC.