



Quality Assurance & Regulatory Affairs
8500 SW Creekside Place
Beaverton, OR 97008

Shutdown in Cold Temperatures

89 units serviced in 2007 and upgraded with software version 02.06.00 have a remote possibility of shut down during use in cold environmental conditions. There are no known injuries or deaths associated with this issue. The units will be updated with the current version of software.